Scope of	f Work for Property Lo	cate	d at	:		4777 North 29tl	h Street		
	Property is: Single Fa	mily		Dup	olex	☑ Other□			
Date:	7/9/2015								
ake no respo		after th	e insp	ection	date	e, or for omissions through	the Redevelopment Authority, and the error or oversight. The list does E programs.		
Exterior	Condition Report								
Location	Required Work					Note/Comments			Cost
Site	Landscaping	n/a		Yes		Self Help		\$	
	Steps/Handrails	n/a		Yes				\$	
	Service walks	n/a	_	Yes				\$	
	Fencing	n/a	✓	Yes				\$	
	Parking	n/a	✓	Yes				\$	
	Retaining walls	n/a	✓	Yes				\$	
	Other	n/a		Yes	V	handrails		\$	350.00
0	Other	n/a		Yes				\$	
Garage	Singles: repair	n/a	V	Yes				\$	
	Shingles: Roof over existing	n/a	V	Yes				\$	
	Shingles:Tear off & re-roof	n/a		Yes	V			\$	1,800.00
	Gutters/downspouts	n/a	V	Yes				\$	
	Flashing	n/a	V	Yes				\$	
	Eaves	n/a		Yes				\$	
	Siding	n/a	V	Yes				\$	
	Doors	n/a		Yes	V			\$	1,100.00
	Windows	n/a	V	Yes				\$	
	Slab	n/a	V	Yes				\$	
	Paint	n/a		Yes	V	all siding and trim		\$	700.00
	Electrical	n/a		Yes				\$	
	Other	n/a		Yes	V	clear brush		\$	500.00
Porches	Doof	2/2		Vaa				Φ.	
	Roof	n/a	<u> </u>	Yes	<u> </u>			\$	
	Deck-upper	n/a		Yes				\$	
	Decklower	n/a		_Yes		_		\$	
	Steps/handrails		V	Yes		_		\$	
	Ceiling	n/a	V	Yes		_		\$	
	Guardrails	n/a	V	Yes				\$	
	Structural	n/a	V	Yes		_		\$	

\$

750.00

n/a ☑ Yes □

n/a 🗌 Yes 🗹 jump porch

Paint

Other

House

Chimney	n/a ☑	Yes □		\$
Shingles: repair	n/a ☑	Yes 🗆		\$
Shingles: Roof over existing	n/a ☑	Yes □	=	\$
Shingles:Tear off & re-roof	n/a □	Yes 🗸		\$ 9,000.00
Gutters/downspouts	n/a □	Yes 🗸		\$ 1,200.00
Flashing	n/a ☑	Yes □		\$
Eaves	n/a ☑	Yes 🗆		\$
Siding	n/a ☑	Yes 🗆		\$
Storm Doors	n/a ☑	Yes □		\$
Prime ("main") Doors	n/a □	Yes ☑	<u> </u>	\$ 1,000.00
Storm Windows	n/a ☑	Yes 🗆		\$
Prime ("main") Windows	n/a 🔲	Yes ☑		\$ 400.00
Paint	n/a ☑	Yes 🗆	-	\$
Foundation	n/a □	Yes ☑	tuck point	\$ 250.00
Electrical	n/a ☑	Yes □		\$
Other	n/a 🗆	Yes 🗆		\$
Other	n/a □	Yes 🗆		\$
Other	n/a □	Yes 🗆	_	\$
Other	n/a □	Yes □		\$

Exterior: Estimated Cost:* \$ 17,050.00

*average contracted cost. Actual costs may vary. Self help will reduce the amount.

interior Co	Unit: Entire unit (single family) Upper unit of duplex					Lower unit of duplex Other		
Mechanical Heating	Required Work							
	Repair/replace boiler	n/a	V	Yes			 \$	
	Repair radiation	n/a	V	Yes			\$	
	Repair/replace furnace	n/a		Yes	V	_	\$	3,300.00
	Repair ductwork	n/a		Yes	V	_	\$	400.00
	Replace thermostat	n/a	V	Yes		_	\$	
	Repair/replace grilles	n/a	V	Yes			\$	
Electrical	Tune boiler/furn. insp ht exchang	€n/a	V	Yes			\$	
Liectificai	Repair/replace receptacles	n/a		Yes	V	_	\$	750.00
	Repair/replace switches	n/a		Yes	V	_	\$	750.00
	Repair/replace fixtures	n/a		Yes	V		\$	1,500.00
	Install outlets and circuits	n/a	V	Yes			\$	
	Install outlets and circuits	n/a	V	Yes			\$	
	Install outlets and circuits	n/a	V	Yes			\$	
	Install outlets and circuits	n/a	V	Yes			\$	
	Upgrade service	n/a		Yes	V		\$	850.00
	Other	n/a		Yes			\$	
DI	Other	n/a		Yes			\$	
Plumbing	Repair/replace kitchen sink	n/a		Yes			\$	
	Repair/replace kitchen sink fauce	e n/a		Yes			\$	
	Repair/replace tub	n/a		Yes			\$	
	Repair/replace tub faucet	n/a		Yes			\$	
	Repair/replace toilet	n/a		Yes			\$	
	Repair/replace lavatory	n/a		Yes			\$	
	Repair/replace lavatory faucet	n/a		Yes			\$	
	Repair/replace wash tub	n/a		Yes			\$	
	Repair/replace wash tub faucet	n/a		Yes			\$	
	Unclog piping:	n/a		Yes			\$	
	Repair drain/waste/vent piping	n/a		Yes	V	_	\$	500.00
	Repair water piping	n/a		Yes	V		\$	750.00
	Repair/replace water heater	n/a		Yes	V	_	\$	750.00
	Other	n/a		Yes	V	Complete kitchen	\$	1,650.00
	Other	n/a		Yes	\checkmark	Complete Bath	\$	2,300.00

Windows	Replace broken glass	n/a ☑	Yes			\$	
	Repair or replace sash	n/a <u></u>	Yes		=	\$	
Doors	Repair or replace doors	n/a □	Yes	V		\$	600.00
	Repair or repl. locks/latches	n/a ☑	Yes		Self Help	\$	
Walls/Ceilin	gs Repair or repl. @ defective	n/a □	Yes	√		\$	3,000.00
Paint	Repair or repl. @ defective	n/a □	Yes	[7]		\$	500.00
Fire Safety	Tropan or ropin & derective	.,,		<u>. </u>		Ψ	
ine Guicty	Install smoke/CO alarm:bsmt.	n/a □	Yes	V	Self Help	\$	50.00
	Install smoke/CO alarm: 1st flr.	n/a □	Yes	V	Self Help	\$	50.00
	Install smoke/CO alarm: 2nd flr.	n/a ☑	Yes		Self Help	\$	
Handrails	Repair/replace defective	n/a □	Yes	V	Self Help	\$	120.00
Stairs	Repair defective	n/a □	Yes	V		\$	450.00
Floors	Repair defective	n/a □	Yes		throughout	\$	2,500.00
Other		n/a □	Yes		mold abatement	\$	500.00
		n/a □	Yes			\$	
		n/a □	Yes		_	\$	
		n/a □	Yes	П		\$	

Interior Co	ondition Report								
Mechanical	Unit: Entire unit (single family) Upper unit of duplex Required Work	□				Lower unit of duplex Other			
Heating	•								
	Repair/replace boiler	n/a	√	Yes				\$	
	Repair radiation	n/a	V	Yes		_		\$	
	Repair/replace furnace	n/a		Yes	V			\$	3,300.00
	Repair ductwork	n/a		Yes	✓			\$	400.00
	Replace thermostat	n/a	V	Yes				 \$	
	Repair/replace grilles	n/a	V	Yes				 \$	
Electrical	Tune boiler/furn. insp ht exchang	j∈n/a	V	Yes				\$	
Liectifical	Repair/replace receptacles	n/a		Yes	V			 \$	750.00
	Repair/replace switches	n/a		Yes	V			\$	750.00
	Repair/replace fixtures	n/a		Yes	V			\$	1,500.00
	Install outlets and circuits	n/a	V	Yes				\$	
	Install outlets and circuits	n/a	V	Yes				\$	
	Install outlets and circuits	n/a	V	Yes				\$	
	Install outlets and circuits	n/a	V	Yes				\$	
	Upgrade service	n/a		Yes	V			\$	850.00
	Other	n/a		Yes				\$	
DI	Other	n/a		Yes				\$	
Plumbing	Repair/replace kitchen sink	n/a		Yes				\$	
	Repair/replace kitchen sink fauce	ein/a		Yes				\$	
	Repair/replace tub	n/a		Yes				\$	
	Repair/replace tub faucet	n/a		Yes				\$	
	Repair/replace toilet	n/a		Yes				\$	
	Repair/replace lavatory	n/a		Yes				\$	
	Repair/replace lavatory faucet	n/a		Yes				\$	
	Repair/replace wash tub	n/a		Yes				\$	
	Repair/replace wash tub faucet	n/a		Yes				\$	
	Unclog piping:	n/a		Yes				\$	
	Repair drain/waste/vent piping	n/a		Yes	V			\$	500.00
	Repair water piping	n/a		Yes	V			\$	750.00
	Repair/replace water heater	n/a		Yes	V			\$	750.00
	Other	n/a		Yes	\checkmark	Complete kitchen		\$	1,650.00

n/a ☐ Yes ☑ Complete Bath

2,300.00

Other

				Total Exterior and Interior Cost:*	\$ 59,540.00
				Interior: Estimated Cost:	\$ 42,490.00
		n/a □	Yes [\$
		n/a 🔲	Yes [\$
		n/a 🔲	Yes [\$
Other		n/a □	Yes 🔽	mold abatement	\$ 500.00
	Repair defective	n/a □	Yes ⊽	throughout	\$ 2,500.00
Stairs Floors	Repair defective	n/a □	Yes 🔽		\$ 450.00
Handrails	Repair/replace defective	n/a □	Yes ⊽	Self Help	\$ 120.00
	Install smoke/CO alarm: 2nd flr.	n/a □	Yes ☑	Self Help	\$ 50.00
	Install smoke/CO alarm: 1st flr.	n/a ☑	Yes [Self Help	\$
Fire Safety	Install smoke/CO alarm:bsmt.	n/a ☑	Yes [Self Help	\$
Paint	Repair or repl. @ defective	n/a □	Yes ☑		\$ 500.00
wans/cening	Repair or repl. @ defective	n/a □	Yes ⊽		\$ 3,000.00
Walls/Ceiling	Repair or repl. locks/latches	n/a 🔽	Yes [Self Help	\$
Doors	Repair or replace doors	n/a □	Yes ⊽		\$ 600.00
_	Repair or replace sash	n/a ☑	Yes [\$
Windows	Replace broken glass	n/a ☑	Yes [\$

Inspected by: Andy Yeager Date: 7/9/15

Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

Important Information Regarding Permits

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located on the first floor of 841 N. Broadway.

 $[\]ensuremath{^*}\text{average}$ contracted cost. Actual costs may vary. Self help will reduce the amount.